







- 13-1030
- 13-1040
- 13-1041
- 13-1050
- 13-1051
- 13-1060
- 13-1070
- 13-1080
- 13-1090




- 23-0030/2000
- 23-0040/2000
- 23-0040/2000
- 23-0050/2000
- 23-0050/2000
- 23-0060/2000
- 23-0070/2000
- 23-0080/2000
- 23-0090/2000




- 20-5081/1650
- 20-5081/1850
- 20-5081/1850
- 20-5081/2050
- 20-5081/2050
- 20-5081/2250
- 20-5081/2550
- 20-5081/2850
- 20-5081/3050




Шуруп
с потайной
головкой




- 13-1030
- 13-1040
- 13-1041
- 13-1050
- 13-1051
- 13-1060
- 13-1070
- 13-1080
- 13-1090




- 23-0030/2000
- 23-0040/2000
- 23-0040/2000
- 23-0050/2000
- 23-0050/2000
- 23-0060/2000
- 23-0070/2000
- 23-0080/2000
- 23-0090/2000




- 31-0303
- 31-0303
- 31-0303
- 31-0305
- 31-0305
- 31-0305
- 31-0307
- 31-0308
- 31-0308




Шуруп
с потайной
головкой





Вариант 1
 Сборка без прокладки





Вариант 2, 3
 Сборка с прокладкой














Шаг 1

Шаг 2

13-0260
 Сухарь
 поворотный

Ось поворота

Ось поворота

40-DIN7 A2
D6x43
 Штифт

40-DIN1481 A2
D5x8
 Штифт

Примечание:
 Перед сверлением отверстий для штифта 40-DIN7 вбейте два штифта 40-DIN1481 для временной фиксации

